## EXHIBIT C

Case: 1:19-cv-05684 Document #: 55-BilEde 0:408912029agag4520689 PageID #: 590

I can meet any night this week after 6pm With Monday and Tuesday being my preference.

You are all welcome to come to my place.

In the meantime, would you mind collecting/sending me the following items:

- all previous correspondence with the board around this or other water issues
- any quotes for work you've had so far, or work you anticipate having
- any other information on work done to mitigate water intrusion other than the recent sealant this summer
- is the roof leaking at all? Has any professional contractor looked at it?
- -names of the contractors used
- anything else you think might be relevant to the conversation.

Perhaps we can use this week's conversation to discuss the history of the building, mitigation done to date, work that you believe is necessary and next steps.

Sounds like we'll need to meet several times to discuss.

Ryan, Has this been disclosed to Your buyer?

Let me know which dates work.

Thanks again for touching base.

Melinda

Sent from my iPhone

On Sep 8, 2018, at 11:01 AM, Young, Melinda < Melinda. Young@nuveen.com > wrote:

Sent with BlackBerry Work (www.blackberry.com)

From: john gorr < jgorr1@msn.com>
Date: Friday, Sep 07, 2018, 8:33 PM

To: Young, Melinda < Melinda. Young@nuveen.com>

Subject: Unit 3 - subfloor damage

Hey Melinda - this is going to be an unfortunate way for us to start talking. I've been very busy trying to sell my place for the past few months and have had several setbacks. I'm not sure what was communicated to you during closing but there has been a history of water intrusion to the building. This has occurred primarily in my unit from leaks through the split face block. The history of the

## Case: 1:19-cv-05684 Document #: 55-3il@ided:402912020a@agt63of83 PageID #:798

water intrusion has been thoroughly documented over some years and was clearly communicated along the way to the other unit owners.

We had the building sealed with elastomeric sealant a few months back so we're fairly confident that the water has stopped getting into the building. However, with the recent inspections on my place a few items have been brought up that have shed light on a new problem. I recently tested positive for elevated levels of mold in my unit. That triggered me to look at replacing some floorboards. Upon removing the floorboards we discovered that the subfloor was severely damaged in many areas and there is mold behind some walls, please see the attached pictures. From what started out as me replacing some floorboards has turned into a large and costly problem that was caused by a building issue. I have spoken with a few contractors about the next steps and the appropriate resolve is to remove some of the subfloor, and much of the drywall on the perimeter of my unit, treat the mold, and then repair and repaint.

I have relayed this information to Ryan as well. I anticipate that you will be surprised and disappointed at this news, and I'm sorry to break it to you. I'll be out of town tomorrow but will be available by phone all weekend to discuss. Otherwise, we can set up a building meeting this week.

John 773-742-0596

<20180904\_154205.jpg>

<20180904\_154518.jpg>

<20180905\_091212.jpg>